CM-QAMB-R02

Product Release Notes

Feature Release

Copyright

About Wellav

Wellav Technologies Ltd. is a leading global provider of professional video delivery solutions. The company is committed to developing and manufacturing world-class video processing, monitoring equipments and solutions to help video service providers address real business challenges in video distribution via HFC and IP-based network. The company is headquartered in Huizhou, China with 500 employees in 2 operation centers and over 10 regional sales/support offices around different continents. With global service, Wellav provides system integration and technical expertise to support more than 2000 CATV, FTTH, IPTV/OTT, Satellite/Terrestrial, Broadband service providers to deliver high-quality video programs to hundred millions of viewers around the world. More information about Wellav is available at the company's website, www.wellav.com.

Revision History

Date	Revision	Description	Author
1/3/2022	1.0	1.4.3 Release Notes	RF
25/3/2022	1.1	1.5.0 Release Notes	RF
19/8/2022	1.2	1.5.30 Release Notes	RF

WELLAV

Table of Contents

WELLAV

Feature Release V1.5.30

Release NO.

CM-QAMB-02_V1.5.30.WVUpgrade

Release Date

August 19, 2022

New Features

1. Add the display for model at the debug interface on the CM-QAMB-02 and CM-QAMB-R02.

2. Merge the 02 and R02 upgrade SW version.

3. Calibrate the QAMB-02 output level

Resolved Issues

1. The link speed which configured by SNMP should limit the input range to [0,2].

2. Use DTU236 for test, it couldn't receive the RF output signal from the 25nd channel. The output bitrate could be displayed normally at Web.

Test Results

positive

Remaining Issues

1. When enable IP output from the CM-QAMB-R02 port1 over 10 channels, it would lead to the port 2 abnormally received the IP signal. When enable the IP output at port2 over 10 channels, it would lead to port1 IP receive abnormal.

2. [CMP+CM-QAMB-R02] Use CM-MOD-02, after configurating the program then change to different slot, click "clear single channel config" button couldn't successfully clear the channel config. And click the "Apply" when the channels has program setting, it would re-configure the same program.

WELLAV

Feature Release V1.5.0

Release NO.

CM-QAMB-02_V1.5.0.WVUpgrade

Release Date

March 25, 2022

New Features

1. Rebuilt the version number from V1.4.18 to V1.5.0.

Resolved Issues

Test Results

positive

Remaining Issues

Feature Release V1.4.3

Release NO.

CM-QAMB-02_V1.4.3_S16087_F735_W16086_20211201.WVUpgrade

Release Date

December 01, 2021

New Feature

1. Added the function to insert MGT, TVCT/CVCT and STT in SI configurations page under ATSC standard.

Resolved Issues

1. Resolved the issue that the audio may loss in modulation output.

Test Results

positive

Remaining Issues

WELLAV

Wellav Technologies Ltd.

No.1, Shunchang Road, Huinan Hi-Tech Industrial Park,

zhongkai Hi-Tech Development Zone,

Huizhou, Guangdong, China 516025

www.wellav.com